10/643 264

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Inventor(s):	Ramaswami et al.		
Patent No.:	6,837,572	**Examiner:**	Mouttet, B.
Issued:	Jan. 4, 2005	**Group Art Unit:**	2853
Title:	Droplet Plate Architecture		

Attorney Docket No.: 10981988-3

RECEIVED
CENTRAL FAX CENTER
FEB 1 1 2005

REQUEST FOR ISSUANCE OF
CERTIFICATE OF CORRECTION

Commissioner for Patents
P.O. Box 1450
Alexandria VA 22313-1450

Sir:

Hewlett-Packard Development Company, L.P., assignee of the entire interest in the above-identified patent, respectfully requests that a Certificate of Correction be issued in accordance with 37 CFR 1.322.

Enclosed herewith are two complete copies of Form PTO 1050 (Rev. 3-82) describing the various errors involved in the above patent. These errors occurred under Rule 322 and appear in Column and Line format.

Issuance of a Certificate of Correction to correct these errors is therefore respectfully requested. We shall appreciate your returning to us one executed copy of this Certificate of Correction for attachment to our Letters patent.

Respectfully submitted,
Ramaswami et al.

By: _____
James R. McDaniel
Attorney for Applicant(s)
Reg. No. 34,481
(208) 396-4095

Intellectual Property Administration, M/S 35
Legal Department
Hewlett-Packard Company
P.O. Box 272400
3404 East Harmony Road
Fort Collins, CO 80527-2400

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO.: 6,837,572
DATED: Jan. 4, 2005
INVENTOR(S): Ramaswami et al.

It is certified that error appears in the above-identified patent and that said letters Patent is hereby corrected as shown below:

Column 7, line 49, delete "beat" and insert in lieu thereof -- heat --;

Column 7, line 54, after "depositing" insert -- a --;

Column 8, line 43, delete "ay" and insert in lieu thereof -- may -- .

PTO Form 1050